

Fast Ion Gauge Guide

Materials: 1: 2.75" Conflat Blank Flange (supplied)

2: SS 304

Quantity: 1

Scale: Full

Tolerances: +/- 0.005" unless otherwise specified

Note: Weld must be vacuum tight.

Julie Mueller

Butler Group

Feb. 1, 2000

2-9003

Section A-A

Cut-outs at non-flange end of tube may be  
filetted slightly if necessary

